

Storage and handling instructions for Nordic Copper

Storage & Transportation


- Keep materials always in dry conditions during the transportation and storage.
- Warm up materials to the room temperature before opening packing to avoid condensation. In cases the material is storage at below 0°C temperature.
- Avoid storage under the direct sunshine.

Protective foil


- Remove foil immediately after installation. Installation here means one single unit/pc, not ready façade or roof. Film is very difficult to remove after some time after installation.
- Evaporated water between foil and metal causes uncertain discolouring and uneven oxidation on the surface.-
- Follow local instructions when disposing the protection foil.

Storage & Transportation


- Coils and sheets must handle with care to avoid scratches and dents.
- Use clean protective gloves when handling materials.
- Avoid oils, grease, mortar, bitumen, paints and all other impurities to stain surface.
- Let the material warm up before opening when moving it from cold place to warm (condensation).
- Avoid walking on wet patinated surfaces (Nordic Blue & Green).
- Don't tape visible areas in cases willing to protect copper surfaces during other treatments on-site. Eg. the painting operation of other areas.




Nordic Standard



Nordic Brown &
Nordic Brown Light



Nordic Green, all finishes




Nordic Blue, all finishes



Nordic Brass &
Nordic Brass Weathered



Nordic Bronze



Nordic Royal



Nordic Décor